

Air Conditioning System Inspection Report

Equipment Owner's Organisation	Bills Bakery
Responsible Site Contact	Bill Bloggs
Equipment Owner's Address	99 Cake Walk, Watford, WD99 9XX
UPRN	012345678900 RRN

Date of inspection	16/11/2009	Date of lodgement	16/11/2009
Assessor name and assessor ID	Russ McAnulla	Address of Assessor's employer	Sheldon Reed Ltd
Name and ID number of Scheme	BREC BREC100010		
Related Party Disclosure			
Assessment Software Used	2		

Executive Summary

Well maintained system. Few obvious problems. Consider changing set point to 27 degrees

System components inspected

The following components of the system were inspected:

System Documentation Refrigeration Plant Heat Rejection Equipment System Controls

Key Recommendations

System efficiency, capacity and cooling loads

No guidance given.

RRN: Inspection Date: 16/11/2009 Page 1 of 2



Air Conditioning System Inspection Report

Improvement options	
No guidance given.	
Alternative solutions	
No guidance given.	
Other recommendations	
No guidance given.	

RRN: Inspection Date: 16/11/2009 Page 2 of 2



Pre Site visit work items:

Equipment Owner					
Organisation Name	Bills Bakery				
Equipment Owner/Manager Name	Bill Bloggs Telephone 01234567890				
Street Address	99 Cake Walk				
City	Watford	Postcode	WD99 9XX		

Equipment Operator (if different from owner)					
Organisation Name	Fred's Fridge Ltd				
Responsible Site Contact	Fred Froid Telephone 09876543210				
Street Address					
City	Glasgow	Postcode	G11 9KK		

Accredited inspector details				
Inspector Name	Russ McAnulla			
Inspector Number		Accreditation Scheme	BREC	
Business Trading Name	Sheldon Reed Ltd			
Business Trading Address	4 Tudor Avenue Watford WD24 7NX			

Insurance Details							
Insurance Company Policy Number							
Start Date	02/10/20	09	Expiry Date	02/10/2009	PI Limit (£)	0

Inspection Details				
UPRN	012345678900	RRN		
Date of inspection	16/11/2009	Date of lodgement		
Effective rated output of the all air-conditioning in the building?	12			

RRN: Inspection Date: 16/11/2009 Page 1 of 10



Note: Request following information from client and complete the following checklist. The inspector should examine the relevant documentation and systems as far as possible to check that the installed equipment is as described. If the documentation is not available, then an additional part of this procedure is to locate the equipment and assemble a minimum portfolio of relevant documentation.

Record Checklist Pre Inspection Information				
Level	Information Required	Reviewed	Not Available	
Essential	Itemised list of installed packaged cooling systems including product makes, models and identification numbers together with cooling capacities and locations of the equipment.	Х		
	Description of method of control of temperature.	Х		
	Description of method of control of periods of operation.	X		
Desirable	Reports from earlier inspections of air conditioning systems, and for the generation of an energy performance certificate			
	Records of maintenance operations carried out including filter changing, cleaning indoor and outdoor heat exchangers, refrigerant leakage tests, repairs to refrigeration components or replenishing with refrigerant.	X		
	Records of calibration and maintenance operations carried out on control systems and sensors			
	Records of sub-metered air conditioning plant use or energy consumption.			
Optional	An estimate of the design cooling load for each system (if available). Otherwise, a brief description of the occupation of the cooled spaces, and of power consuming equipment normally used in those spaces.			
	Records of any issues or complaints that have been raised concerning the indoor comfort conditions achieved in the treated spaces.	X		

RRN: Inspection Date: 16/11/2009 Page 2 of 10



rackayeu coomi	g Systems inspection offectilst	
Site visit work items	S:	
Number of Units	2	
Equipment inspector actual verified information	ed Note: Verify information provided by client is correct by we n in fields below.	ay of inspection and insert
Unit Identifier	Outside Unit	
Manufacturer	Dakin	
Description	Outside unit of multi-split system	
Model / Reference	Unknown	
Serial Number	N/A	
Year plant installed	2006	
Rated Cooling Capacity (kW)	13	
Refrigerant Type	R-22	
Location	Roof	
Areas / Systems Served	Whole area	
Note below any discrepa	ncy between information provided by client and on site inform	nation collected:
Packaged Cooling	Units checklist for visual inspection	
Item / Guidance Notes	Inspection Notes	Guidance Recommendations
Is area around	Yes □ No ⊠	No guidance given.
equipment clear of obstructions and debris, both to operators and to airflow?	If No provide information and description of obstructions:	
Is general condition of	Yes ⊠ No □	No guidance given.
the indoor and/or outdoor units in good order?	If no provide description of dilapidations:	
Assess temperature difference / and observe refrigerant via sight	Yes ⊠ No □	No guidance given.

RRN: Inspection Date: 16/11/2009 Page 3 of 10



glass or pressure gauge. Is this satisfactory?	If no provide explanation:	
Is the heat exchanger partially blocked or undersized?	Yes □ No ☒ If yes provide explanation:	No guidance given.
Is there evidence of icing or excessive condensation?	Yes □ No ⊠ If yes provide detail:	No guidance given.
Does area around plant show signs of oily stains indicative of a refrigerant leak?	Yes □ No ☒ If yes provide description and check any notes within the maintenance records :	No guidance given.
Are there any obstructions to airflow through the outdoor and indoor unit heat exchangers?	Yes □ No ⊠ If yes provide description	No guidance given.
Is there any potential for recirculation of warm air?	Yes □ No ⊠ If yes provide explanation:	No guidance given.
Check condition of indoor grilles, filters and terminal units.		

Appropriately Size	d Cooling Plant			
Guidance Notes	Inspection Notes			Guidance Recommendations
Compare system sizes	Following Information Requ	ired:		No guidance given.
with likely loads. Section 4 TM44	Total Occupants	0		
contains simple	Total Floor Area	250		
procedures for assessing whether	Occupant density /m ² derive	5		
refrigeration systems				
and air supply systems are likely to be	Lower level heat gain	10	/W m ²	
oversized.	Upper level heat gain	14	/W m ²	

RRN: Inspection Date: 16/11/2009 Page 4 of 10



Installed Cooling Capacity	y 13	kW	
The installed size is dee	emed:		
More than Expected			
Less than Expected			
As Expected			

Refrigeration Charge				
Guidance Notes	Inspection Notes		Guidance Recommendations	
In operation observe	Refrigeration Temperature:		No guidance given.	
the temperature difference across the	Pre compressor	0		
refrigeration	Post Compressor	0		
compressor. Compared with the ambient	Ambient	0		
temperature in the plant				
room / outside air.	The Temperature is Deemed:			
	More than Expected			
	Less than Expected			
	As Expected			

Metering					
Item / Guidance Notes	Inspection Notes	Guidance Recommendations			
Is metering installed to enable monitoring of energy consumption of refrigeration plant?	Yes □ No ☒ If yes, record meter reading	No guidance given.			
Is a BEMs installed in the building which can warn about out of range alarms?	Yes □ No ☒ If No then provide details No BEM system in place	No guidance given.			

Equipment inspected Note: Verify information provided by client is correct by way of inspection and insert

RRN: Inspection Date: 16/11/2009 Page 5 of 10



actual verified information in fields below.					
Unit Identifier	Inside Unit				
Manufacturer	Dakin				
Description	One of 3 cassettes				
Model / Reference	Cassette				
Serial Number	N/A				
Year plant installed	2006				
Rated Cooling Capacity (kW)	4				
Refrigerant Type	R-22				
Location	Main office				
Areas / Systems Served	Whole area				

Note below any discrepancy between information provided by client and on site information collected:

Packaged Cooling Units checklist for visual inspection				
Item / Guidance Notes	Inspection Notes	Guidance Recommendations		
Is area around equipment clear of obstructions and debris, both to operators and to airflow?	Yes □ No ☒ If No provide information and description of obstructions:	No guidance given.		
Is general condition of the indoor and/or outdoor units in good order?	Yes □ No ☒ If no provide description of dilapidations:	No guidance given.		
Assess temperature difference / and observe refrigerant via sight glass or pressure gauge. Is this satisfactory?	Yes ☑ No □ If no provide explanation:	No guidance given.		
Is the heat exchanger partially blocked or undersized?	Yes □ No ⊠ If yes provide explanation:	No guidance given.		

RRN: Inspection Date: 16/11/2009 Page 6 of 10



Is there evidence of icing or excessive	Yes □ No ⊠	No guidance given.
condensation?	If yes provide detail:	
Does area around plant show signs of oily stains indicative of a refrigerant leak?	Yes □ No ☒ If yes provide description and check any notes within the maintenance records :	No guidance given.
Are there any obstructions to airflow through the outdoor and indoor unit heat exchangers?	Yes □ No ☒ If yes provide description	No guidance given.
Is there any potential for recirculation of warm air?	Yes □ No ☒ If yes provide explanation:	No guidance given.
Check condition of indoor grilles, filters and terminal units.	All filters and grills clean	

Guidance Notes	Inspection Notes	Guidance Recommendations		
Compare system sizes	Following Information Requ	No guidance given.		
with likely loads. Section 4 TM44	Total Occupants	0		
contains simple	Total Floor Area	50		
procedures for assessing whether refrigeration systems	Occupant density /m ² derive	5		
and air supply systems are likely to be	Lower level heat gain	3	/W m ²	
oversized.	Upper level heat gain	5	/W m ²	
	Installed Cooling Capacity	4	kW	
	The installed size is deemed	 d:		
	More than Expected			
	Less than Expected			
	As Expected	\boxtimes		

RRN: Inspection Date: 16/11/2009 Page 7 of 10



Refrigeration Charge				
Guidance Notes	Inspection Notes		Guidance Recommendations	
In operation observe	Refrigeration Temperature:		No guidance given.	
the temperature difference across the	Pre compressor	0		
refrigeration	Post Compressor	0		
compressor. Compared with the ambient temperature in the plant	Ambient	0		
room / outside air.				
	The Temperature is Deemed			
	More than Expected			
	Less than Expected			
	As Expected			

Metering		
Item / Guidance Notes	Inspection Notes	Guidance Recommendations
Is metering installed to enable monitoring of energy consumption of refrigeration plant?	Yes □ No □ If yes, record meter reading	No guidance given.
warn about out of range	Yes □ No ☒ If No then provide details None necessary with such a small installation	No guidance given.

RRN: Inspection Date: 16/11/2009 Page 8 of 10



System Controls		
Item / Guidance Notes	Inspection Notes	Guidance Recommendations
Assess zoning in relation to factors such as local levels of internal gain, orientation and exposure to solar radiation. Is zoning appropriate?	Yes ⊠ No □ If no explain problem:	No guidance given.
Note the current indicated weekday and time of day on controllers against the actual time.	Correct	No guidance given.
Note the set on and off periods (for weekday and weekend if this facility is available with the timer).	Setting appropriate to staff working hours	No guidance given.
Is there a shortfall in timer capabilities?	Yes □ No ⊠ If yes explain problem:	No guidance given.
Identify and assess zone heating and cooling temperature control sensors. Are the sensor types and locations appropriate in relation to heating and cooling emitters, heat flows or likely temperature distributions in the zone or space?	Yes ⊠ No □ If no explain problem:	No guidance given.
Note the set temperature in each zone for heating and cooling in relation to the activities and occupancy of zones and spaces in relation to the manager's intent.	set to 22 degrees	Consider resetting to 27 degrees

RRN: Inspection Date: 16/11/2009 Page 9 of 10



Are guidance notices	Yes	\boxtimes	No □	No guidance given.
visible or controls available to inhibit use of cooling equipment whilst windows are open or cooling/heating is on?	If yes	explai	n problem:	
Note type, age and method of capacity of control equipment.	Week	end se	ettings available	No guidance given.
Compare with current good practice	ОК			No guidance given.



RRN: Inspection Date: 16/11/2009 Page 10 of 10